

# **Navajo Abandoned Uranium Mine Site Screen Report**

*This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits and pits. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites lands not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands but that are or may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.*

*The purpose of the form is to ascertain the status and location of the identified AUM site, to record all immediate site information associated with the mine site and to document the recommendation and/or decision on what additional steps, if any, are needed at the site.*

**Hogback No. 4 AUM Site**

**Navajo AUM Eastern Region**

**Prepared by:**

**Weston Solutions, Inc.**

**Contract: W91238-06-F-0083**

**12767.063.496.1111**

**May 2009**

**Part I Site Identification, Location and Status****Site Names and ID numbers as applicable****Mine ID:** 312**Map ID:** E17**CERCLIS:** NNN 000 908 722**NAMLRP:** NOT ASSIGNED**New Mexico Mining and Mineral Division ID:** NM0092**New Mexico Bureau of Geology and Mineral Resources:** NMMK0083**Local name / Aliases:** Hogback No. 3-5, Hogback, Haystack No. 12, Hyde, Tucker, Davenport**Chapter and local area:** Church Rock Chapter**Lat/Long:** 35.5467008126 N / -108.692313658 W**Nearby road and highway:** NM-566, Interstate 40**Local Post Office:** Church Rock, NM**Land Status: check one or more and provide ownership and contact information below**

<b>Tribal Trust Land</b>	<input type="checkbox"/>
<b>Tribal Fee Land</b>	<input type="checkbox"/>
<b>Allotment</b>	<input type="checkbox"/>
<b>Fee land</b>	<input type="checkbox"/>
<b>Public lands</b>	<input type="checkbox"/>
<b>Private</b>	<input type="checkbox"/>
<b>Bureau of Land Mgmt</b>	<input checked="" type="checkbox"/>
<b>State</b>	<input type="checkbox"/>

**Ownership and contact information:**

No ownership was identified. The mine site property is classified as Bureau of Land Management land.

**Part II        Site Observations**

**Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:**

**0 to 200 feet:** None                    **200 feet to 0.25 mile:** None

**Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:**

**0 to 200 feet:** None                    **200 feet to 0.25 mile:** None

**Levels measured around the perimeter(s) of the identified structure(s):**

None

**Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:**

**0 to 0.25 miles:** None                    **0.25 miles to 4 miles:** None

**Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.**

None observed

**Known Site History: include information from interviews with Chapter officials and residents.**

**Note information on mine ownership, period of operation, and type of mining operation.**

Hogback No. 4 mine consists of an area of 22,016.64 square meters. Any historical information pertaining to mining operations and historical ownership of the mine site appeared to be unclear.

**Part III        Type, number and reclamation status of mine features**

**Provide description and reclamation status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all reclamation caps.**

Reclamation status of the mine site is currently unknown. No visible signs of reclamation were observed. Several large piles of gravel were located throughout the site property. No adits or other mine features were observed during the site visit.

**Part IV        Summary of radiological readings****Background Locations**

#1 12,575 cpm

#2 12,727 cpm

**Mine site:** Hogback No. 4

- See Figures 1 and 2

**Nearby Structure Perimeter** – None**Describe any other radiological measurements:**

A total of 2,058 gamma radiation measurements were collected from mine sites, ranging from 17,931 cpm to 515,237 cpm. The measurements are represented in Figures 1 and 2.

**Part V        Site sketch of all mine features and readings, including locations of all structures, sources of drinking water and any other important features and radiological readings.**

Presented in Figures 1 and 2

## **Part VI        Response Action Summary**

**Site Name(s):** Hogback No. 4      **Chapter:** Church Rock

### **Decision Criteria**

**Is there an unreclaimed waste pile at the site?** No

**At what distance from the waste pile is the nearest residential structure located?** N/A

**At what distances from the waste pile are there potential drinking water sources?** N/A

**Is there a reclamation cap or sealed adit in place at the site?** No

**Is the cap/seal functionally intact?** N/A

**Is the cap/seal sufficiently degraded to create a concern about releases?** N/A

**At what distance from the cap/seal is the nearest domestic structure located?** N/A

**At what distance from the cap/seal is the nearest domestic drinking water source?** N/A

### **Summary of emergency response factors**

None

### **Summary hazard ranking system factors**

None

### **Summary of reclamation factors**

No known reclamation

## Part VII Photos



Photo 1. Hogback No 4 mine site and grading, towards the north



Photo 2. Hogback No 4 mine site, area with dark soil, towards the southeast



Photo 3. Hogback No 4 mine site southern gravel slope, Gallup in the distance, towards the southeast



Photo 4. Hogback No 4 mine site cliff area, towards the south

## Part VIII Contacts Reports and Information

Name Stanley Edison

Title or official role (if any) Navajo EPA Superfund Program

Address PO Box 2946, Window Rock, AZ 86515

Information provided General Background and Contact/Access Information

---

Name \_\_\_\_\_

Title or official role (if any) \_\_\_\_\_

Telephone number \_\_\_\_\_

Information provided \_\_\_\_\_

---

Name \_\_\_\_\_

Title or official role (if any) \_\_\_\_\_

Telephone number \_\_\_\_\_

Information provided \_\_\_\_\_

---


Name \_\_\_\_\_

Title or official role (if any) \_\_\_\_\_

Telephone number \_\_\_\_\_

Information provided \_\_\_\_\_

---



## Legend

### Gamma Radiation Measurements

- 0 - 10,000
- 10,000 - 15,000
- 15,000 - 20,000
- 20,000 - 50,000
- 50,000 - 100,000
- > 100,000

■ Mine Claim Boundaries



Gamma survey conducted in October 2008  
measured as counts per minute

Hogback No. 4



Gamma Radiation Measurements  
Hogback No. 4  
Church Rock Chapter  
Navajo Nation, New Mexico